# TEST REPORT

**No. : XMIN1509005443ML**
**Date : Sep 16, 2015**
**Page: 1 of 2**

CUSTOMER NAME: XIAMEN GOOMAX ENERGY TECHNOLOGY CO., LTD
ADDRESS: 905# JORDAN BUILDING, HIGH-TECH PARK, HULI DISTRICT, XIAMEN CHINA

The following sample(s) was/ were submitted and identified on behalf of the client as:

| | | |
|---|---|---|
| Sample Name | : | METAL ROOF CLIPS |
| Date of Receipt | : | Sep 02, 2015 |
| Testing Start Date | : | Sep 06, 2015 |
| Testing End Date | : | Sep 11, 2015 |
| Test result(s) | : | For further details, please refer to the following page(s) |

Signed for
SGS-CSTC Standards Technical Services Co. , Ltd Xiamen Branch Testing Center

Hank Li
Authorized signatory

Note: Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
No.31 Xianghong Road, Xiang'An Torch Industrial Zone, Xiamen, Fujian Province, China. 361101 t (86-592) 5761588 f (86-592) 5765380 www.sgsgroup.com.cn
中国·福建·厦门·火炬（翔安）产业区翔虹路31号 邮编:361101 t (86-592) 5761588 f (86-592) 5765380 e sgs.china@sgs.com
Member of the SGS Group (SGS SA)

# TEST REPORT

**No. : XMIN1509005443ML**
**Date : Sep 16, 2015**


Pull Test:

Test Method: As the client's requirement.

Fix the sample as photo 1 & photo 2. Load force with 10mm/min. Determine the max force

Test Result:

| Test item | Test result |
|---|---|
| Pull test | When the sample destruction (see photo 3) the maximum force (F) 2.822KN |

Test Photo:

Photo 1: Sample

Photo 2:Before the test




Photo 3: After the test




Photo 4:Force–displacement curve

******** End of report********

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

No.31 Xianghong Road, Xiang'An Torch Industrial Zone, Xiamen, Fujian Province, China. 361101 t (86-592) 5761588 f (86-592) 5765380 www.sgsgroup.com.cn
中国·福建·厦门·火炬（翔安）产业区翔虹路31号 邮编:361101 t (86-592) 5761588 f (86-592) 5765380 e sgs.china@sgs.com

Member of the SGS Group (SGS SA)